

Photograph 1. Looking east on Bennett Street, from just west of Bennett Street bridge.



Photograph 2. Homes on south side of Bennett Street between Jefferson Avenue and Bennett Street bridge.




Photograph 3. Looking east on Bennett Street just west of Jefferson Avenue.



Photograph 4. Looking west on Bennett Street from just west of Jefferson Avenue.




Photograph 5. Homes on south side of Bennett Street, east of Jefferson Avenue.




Photograph 6. Homes on north side of Bennett Street, east of Jefferson Avenue.



Photograph 7. Fassnight Creek channel immediately upstream from Holland Avenue.




Photograph 8. Fassnight Creek channel immediately upstream from Holland Avenue.




Photograph 9. Fassnight Creek transition from open channel to box culvert flow, at Holland Avenue.




Photograph 10. End of box culvert reach of Fassnight Creek, at Jefferson Avenue.



Photograph 11. Fassnight channel between Bennett Street bridge and Jefferson Avenue.



Photograph 12. Fassnight channel between Bennett Street bridge and Jefferson Avenue.



Photograph 13. Fassnight channel between Bennett Street bridge and Jefferson Avenue.



Photograph 14. Fassnight channel between Bennett Street bridge and Jefferson Avenue.



Photograph 15. Fassnight channel between Bennett Street bridge and Jefferson Avenue.



Photograph 16. Bennett Street bridge, looking downstream.



Photograph 17. Bennett Street bridge, looking downstream.




Photograph 18. Bennett Street bridge, looking downstream.



Photograph 19. Bennett Street bridge, looking upstream.




Photograph 20. Fassnight Creek channel downstream of Bennett Street bridge.




Photograph 21. Fassnight Creek channel downstream of Bennett Street bridge.



Photograph 22. Fassnight Creek channel downstream of Bennett Street bridge.



Photograph 23. Mr. Warren Rankin (251 E. Bennett Street) pointing to maximum flood depth at his home, which occurred during 1993 flood.



Photograph 24. During the 1993 flood, Mr. Warren Rankin reported that the flood depth reached the top of his bottom step.



Photograph 25. Location of Mr. Warren Rankin's house relative to the Bennett Street bridge (looking to the northeast).



Photograph 26. Looking southeast toward Bennett Street from Mr. Greg Davison's residence between Jefferson Avenue and Bennett Street bridge; note chain link fence where flood levels have been observed and measured.